



connect the positive pole of the push-button panel to terminal **A**
 Connect the positive pole from the lane of the track to terminal **B**
 (optional) To have maximum braking when the power supply is disconnected, connect the negative pole of the lane of the track to terminal **C**